ATION REPORT

INFORMATION REPORT


CENTRAL INTELLIGENCE AGENCY


		ness Desence of the United States within the meaning of the liation of which in any manner to an unauthorized person	50X1-HUM
UNTRY	East Germany	REPORT	
BJECT	Stendal Airfield: Status as July 1959; (fuel dump of containers)	DATE DISTR. 27 OCT 1959 + Capacita NO PAGES 3	
		REFERENCES	
TE OF O. .CE & TE ACQ.			50X1-HUM
L ACQ.	SOURCE EVALUATIONS ARE DEFIN	NITIVE. APPRAISAL OF CONTENT IS TENTATIVE.	50X1-HUM
w [*] .	The construction order ver construction of a congrete	1959 that the encasing with concrete to 4 at Stendal airfield was intensificablly good: Concreting of fuel contact or road. ere shifted from Wandlitz construction shows there since the target date here.	iners and 50X1-HU
	projected new fuel dump No since 1958. The project of parallel rows of container containers with the larger required interval between	rmation refers to the o 4 at Stendal airfield, as has been 1 f the new fuel dump (T 4) provides for rs. Each row consists of two large and r ones at the ends of the row. There	two
	For sketch of fuel dump ar Annex 1.	the individual containers and the two	s the
	Annex 1. 2. Comment. After comfield between 1956 and 195 Tiefbau Brandenburg) had t field was taken over by th available fuel dumps (T 1- were not yet remained by t	mpletion of the runway system at Stend 53, VEB-ITB (Volkseigener Betrieb-Inge to vacate the field. Subsequently, the as Soviets and occupied by them later 3) which had been established before	50X1-HU al air- nieur- on. The
	Annex 1. 2. Comment. After comfield between 1956 and 195 Tiefbau Brandenburg) had t field was taken over by th available fuel dumps (T 1- were not yet remained by t	mpletion of the runway system at Stend myletion of the runway system at Stend 38, VEB-ITB (Volkseigener Betrieb-Inge to vacate the field. Subsequently, the se Soviets and occupied by them later 3) which had been established before that time. Since no new fuel dumps were ald ones would be made ready for opera	50X1-HU al air- nieur- on. The 1945, e observed tion.
	Annex 1. 2. Comment. After comfield between 1956 and 195 Tiefbau Brandenburg) had t field was taken over by th available fuel dumps (T 1- were not yet repaired by t it was expected that the o	mpletion of the runway system at Stend myletion of the runway system at Stend 38, VEB-ITB (Volkseigener Betrieb-Inge to vacate the field. Subsequently, the se Soviets and occupied by them later 3) which had been established before that time. Since no new fuel dumps were ald ones would be made ready for opera	50X1-HU al air- nieur- air- on. The 1945, e observed tion. ter- 50X1-HU
	Annex 1. 2. Comment. After comfield between 1956 and 195 Tiefbau Brandenburg) had t field was taken over by th available fuel dumps (T 1- were not yet repaired by t it was expected that the o	mpletion of the runway system at Stend pletion of the substance of the Soviets and occupied by them later pletion of the system	50X1-HU al air- nieur- on. The 1945, e observed tion.

NEORMATION REPORT

(NOTE: HEADQUARTERS DISTRIBUTION INDICATED BY "X": FIELD DISTRIBUTION BY "#".)

	9.47.4.4.9.50			V4 I
			50.	X1-ŀ
<i>)</i>				
	- 2 -	*	50X1-HU	11/4
	- 2 -		3071-11	ועוכ
	1			
1 - 4 containers			t	
2 - 3 containers				
3 - 6 containers			t	
	. Their holding capaci			
ee attachments.	(T 4) and detailed infehments: A map of the			i
	enments: A map of the			
facilities as of Jul	Ly 1959.			
· 	· 			
				· ·
				*
				•
				•
		51	OX1-HIIM	•
		51	0X1-HUM	
		51	0X1-HUM	
		51	0X1-HUM	
		5	0X1-HUM	•
		5	0X1-HUM	
		5	0X1-HUM	
		51	0X1-HUM	
		51	0X1-HUM	
		5	0X1-HUM	
		5	0X1-HUM	
		51	0X1-HUM	
		51	0X1-HUM	
		5	0X1-HUM	





Barracks of former German period,

still available?

Bar 3 4 barracks in southwestern corner of

field, near target ranges

Lighting facilities

Runway lights Permanent lights on both sides

Obstacle lights On masts along optical approach line

Flare path Possibly available in eastern

extension of runway

Aircraft revetments About 30 revetments along eastern and

southern edges of airfield

Transformer house in "Neues Lager", east of highway No 189

Flight control

Building of former German period at station northern edge of landing field; in this

building also housing fire department

and weather station

Sanitized Copy Approved for Release 2010/08/10 : CIA-RDP80T00246A051300050001-6

S-E-C-R-F-T

50X1-HUM

س 3 **ـ**ـ

Items Information AA gun emplacement east of airfield, north of "Neues Lager", presumably evacuated. In southwestern corner of airfield, occupation unknown so far Radio installations: Fu A: Type A dismantled Fu C: Type C in eastern extension of runway, west of Stendal-Baben road Fu D: Type D location now known Garages: G 1, G 2 in northwestern corner of airfield, 1) along old taxiway G 3 wo temporary building serving as garages, southwest of entrance to airfield 50X1-HUM "Neues Lager": G 1 large garage G 2 motor vehicle sheds Hangars: H 1, 2, 3 undestoyed and/or rebuilt H 4, 5, 6, 6a destroyed; reconstruction unknown Adjustment and Target ranges in southwestern corner of airfield; adjustment stand target ranges allegedly in northwestern commer of landing field Kitchens, Culture buildings K l Kitchen

Kitchen and messhall in brick barracks

S-E-C-R-E-T

still serving as such

Former officer's club, presumably

50X1-HUM

K 2

"Neues Lager"

S-E-C-R-E-T

50X1-HUM

-4-

Items	Information
Ammunition dump	about 300 m square, northwest of airfield in small wood; 3 barracks, each 30 x 10 m, bombs piled up in the open, earth bunkers, wooden fence, 4 watch towers
Pump house	presumably belonging to fuel dump (T 4)
Taxiways: R 1	old taxiway, presumably leading to camouflaged parking places and hangars
R 2	new taxiway, 14 m wide, not drained.
Ruxway ;	direction: SWS-ENE length: 2,000 m width: 60 m thickness: 18-20 cm
*	drained on both sides; optical flight base line in eastern extension
Sheds:	
Schp 1	storing coal
Schp 2	storing cement
Sports ground	
Fuel dump:	
T 1	located in western bend of spur track; 4 - 5 containers, each holding 30,000 liters
Т 2	2 underground containers; size u/i
Т 3	6 containers; size u/1
T 4	new fuel dump west of T l, size u/i
"Neues Lager"	50 barrels each holding 200 liters, in wooden sheds

S-E-C-R-F-T

50X1-HUM

Sanitized Copy Approved for Release 2010/08/10 : CIA-RDP80T00246A051300050001-6 S-E-C-R-E-T 50X1-HUM - 5 -Items Information Quarters 01 villa near field entrance, in poor condition U 2 4 quartering buildings "Neues Lager" 3 brick barracks (U 1-3) Dispatch office Administration komendatura north of main road through building airfield; flight control building (F) also called headquarters building Repair hangar building west of hangar No 3 Guardhouse at entrance in northeastern corner of the airfield; guardhouse in "Neues Lager" Ordnance shop ∍i) Watch towers l each at corners of ammunition dump Fence $^{\rm Z}$ B Board fence wire fence

S-E-C-R-E-T	7		5074 1111
			50X1-HUN
		1	